

SHREERAM KULKARNI

B.E. (Civil) M.E. (Structures) A.M.I.E. (India)



————— **STRUCTURAL CONSULTANT & CHARTERED ENGINEER**

Office & Residence :
'Maitri', 484, Sardarbaazar, Old P.T.O. Satara.
Off. : 232965, 228705, Resi. : 236994
Mobile : 9822057378, 9284334693
E-mail : sakulkarni03@gmail.com

Date:- 15/02/2019

STRUCTURAL STABILITY REPORT

**Structural Stability Report Of various Buildings at Mary Matha School
Pingali,Dhahiwadi,
Dist-Satara,Maharashtra.**

The undersigned visited Mary Matha School Pingali,Dhahiwadi, Dist-Satara , Maharashtra , to make report of its stability accordingly the undersigned inspected Classrooms ,Teacher Rooms , Library & Science Laboratory , Computer lab in the said property on Tuesday 12th Feb 2019 @ 12 noon.

My observations & emerging recommendations are as under:

Observations :

- 1) All Building are Ground + First Floor RCC Building.
- 2) All the building within campus are well maintained.
- 3) All RCC buildings found intact & without any structural deformation.

Recommendation :

- 1) Considering all the observations, Classrooms ,Teacher Rooms , Library & Science Laboratory , Computer lab at Mary Matha School Pingali, Dhahiwadi, Dist- Satara , Maharashtra are structurally sound & safe for their intended use.


SHREERAM KULKARNI.


Principal
Mary Matha English Medium School
C.B.S.E. Affi.No.1130966
Pingli(Bk) Dahiwadi, Maharashtra
Pin-415506